




① BOX UNFOLDED, PAPER TWINE IN PLACE. LAY FLEECE FLESH SIDE DOWN WITH CLEAN TAGS & LOOSE ENDS IN THE CENTER.



② RAISE & HOLD SIDES




③ RAISE ENDS, CLOSING AND LOCKING THE BOX. TIE FLEECE.



④ RELEASE ENDS, UNFOLDING BOX. WEIGH, TAG, AND PACK FLEECE IN WOOL BAG.

OPERATION OF THE WOOL BOX



NOTES:
1. DIMENSIONS SHOWN ARE BASED ON USE OF STANDARD 1" x 12" LUMBER DRESSED. THIS IS ADEQUATE FOR FLEECE OF 8 TO 10 POUNDS.

2. THE PLAN MAY BE MODIFIED AS DESIRED TO SUIT INDIVIDUAL PREFERENCES.

3. ALL WOOD PARTS SHOULD BE SANDED & CORNERS SMOOTHLY ROUNDED; REMOVE CORNERS & BURRS FROM METAL PARTS TO AVOID SNAGGING WOOL.

4. TIE FLEECE WITH PAPER TWINE ONLY.

PLAN EX. 5806 SHOWS DETAILS OF A WOOL PACKING RACK WHICH HOLDS THE WOOL BAG IN A CONVENIENT POSITION.

CUTTING & ASSEMBLY DIAGRAM

COOPERATIVE EXTENSION WORK IN AGRICULTURE AND HOME ECONOMICS DEPARTMENT OF AGRICULTURAL ENGINEERING UNIVERSITY OF MARYLAND AND UNITED STATES DEPARTMENT OF AGRICULTURE COOPERATING		
WOOL BOX FOR TYING FLEECE		
MASS. '55	EX. 5805	SHEET 1 OF 1